

PRODUCT RECALL NOTICE



Approximately 169,000 push-button Pindicator fire extinguishers were sold in the UK between 1995 and 2006. Approximately 700 plastic handle fire extinguishers were sold in the UK between 2011/2012.

Affected fire extinguishers can become clogged or require excessive force to discharge and can fail to activate during a fire emergency. In addition, in some models, the nozzle may detach with enough force to pose an impact hazard.

Kidde is not aware of any incidents in the United Kingdom and other EU/EEA Member States involving the affected products. However, in the United States and Canada, Kidde has received approximately 391 reports of limited or failed activation or nozzle detachment.



The model number is printed on the fire extinguisher label

The tables below show the model numbers of the affected fire extinguishers:

Plastic Handle Fire Extinguishers Affected Models in UK
Model Number
H110G
FA110G
M110G
FC110
FS110
M110GM

Push-Button Pindicator Fire Extinguishers Affected Models in UK
Model Number
KK2
100D
M5P
M5PM
210D
AUTO 5FX

What You Should Do

Consumers should immediately visit www.kiddesafetyeuroperecall.com or call (UK) 0800 088 5513 or (UK customers calling from outside the UK) +44 (0) 208 0891702 to request a free replacement fire extinguisher and for instructions on returning the recalled unit, as it may not work properly in a fire emergency.